

TEST PIT DATA REQUIRED TO BE SUBMITTED WITH APPLICATION

DESCRIPTION OF SOILS ENCOUNTERED IN TEST HOLES

DEPTH G.L.	HOLE NO. <u>1</u>	HOLE NO. <u>2</u>	HOLE NO. <u>3</u>	HOLE NO. <u>4</u>
6"	0" to 6" topsoil ↓	0" to 6" topsoil ↓	0" to 6" topsoil ↓	0" to 6" topsoil ↓
12"				
18"				
24"	6" to 74"	6" to 80"	6" to 77"	6" to 77"
30"	medium sandy	medium sandy	medium sandy	medium sandy
36"	loam with gravel	loam with gravel	loam with gravel	loam with gravel
42"	and cobbles	and cobbles	and cobbles	and cobbles
48"	possible prior fill	possible prior fill	possible prior fill	possible prior fill
54"				
60"				
66"				
72"				
78"	↓		↓	↓
84"		↓		

WAS GROUNDWATER ENCOUNTERED? YES/NOINDICATE LEVEL AT WHICH GROUND WATER IS ENCOUNTERED n.a. Ft/InINDICATED LEVEL FOR WHICH WATER LEVEL RISES AFTER BEING ENCOUNTERED n.a. Ft/InDEEP TEST MADE BY Alan L. Pilch, PEDATE OF DEEP TESTS 11/18/2025WCDOH PERSONNEL PRESENT: Wayne Schneider

DESIGN

Soil Rate Used 31 to 45 Min/1" Drop:

S.D. Usable Area Provided _____

No. of Bedrooms n.a. Septic Tank Capacity 1,000 Gals. Masonry X Metal _____Absorption Area Prov. by 175 L.F. x 24" _____ width trench. Other _____Name Alan L. Pilch, ALP Engineering & Land Arch

Signature _____

Address P.O. Box 843
Ridgefield, CT 06877

Seal

Westchester County Health Department

Soil Rate Approved _____ Sq. Ft./Gal

Checked by _____

S.D. 27.6

1/22